

REQUEST FOR QUOTATION

REFERENCE NO.: MR24-02-025

We are inviting all interested contractors/suppliers to submit their best quotation for the **PROCUREMENT FOR THE SUPPLY OF LABOR AND MATERIALS FOR THE REPAIR OF VARIOUS NDC SERVICE VEHICLES:**

Requirements:

Requirement	Qty	Estimated Unit Cost	Estimated Total Cost
I. Isuzu Sportivo SHY 224:			
A. Part/Consumable to be supplied:			
1. Center Link	1 pc	4,200.00	4,200.00
2. Tierod End	4 pcs	980.00	3,920.00
3. Ball joint upper	2 pcs	1,500.00	3,000.00
4. Ball joint lower	2 pcs	1,800.00	3,600.00
B. Labor:			
1. Replacement of Center link, Tierod end, & Ball joint upper & lower	1 lot	2,300.00	2,300.00
2. Wheel alignment and camber correction	1 lot	1,500.00	1,500.00
Sub-Total			18,520.00
II. Toyota Innova SAA 7935:			
A. Part/Consumable to be supplied:			
1. Tierod End	2 pcs	1,100.00	2,200.00
2. Tierod Bar	2 pcs	1,300.00	2,600.00
3. Stab linkage	2 pcs	1,400.00	2,800.00
4. Stab Clamp	2 pcs	350.00	700.00
5. Shock Front	2 pcs	3,900.00	7,800.00
6. Ball joint upper	2 pcs	1,800.00	3,600.00
7. Ball joint lower	2 pcs	1,400.00	2,800.00
8. Suspension bushing upper	4 pcs	680.00	2,720.00
9. Brake shoe	1 set	1,900.00	1,900.00
10. Brake pad	1 set	1,800.00	1,800.00
B. Labor			
1. Replacement of Tierod end, Tierod Bar, Stab linkage Stab clamp, Front Shock, Ball joint upper & lower, and Suspension bushing upper.	1 lot	7,000.00	7,000.00
2. Wheel alignment and camber correction	1 lot	1,500.00	1,500.00
3. Reface of brake drum	2 pcs	1,800.00	3,600.00
4. Replacement of brake shoe	1 lot	900.00	900.00
5. Replacement of brake pad	1 lot	700.00	700.00
Sub-Total			42,620.00

III. Hyundai Starex SKC 255:			
A. Part/Consumable to be supplied:			
1. Drive belt	2 pcs	3,600.00	7,200.00
2. Idler bearing	1 pc	5,600.00	5,600.00
3. Idler tensioner	1 pc	3,400.00	3,400.00
B. Tinsmith			
1. Remove and re-install left and right sliding door	1 lot	11,800.00	11,800.00
Repair left and right sliding door striker			
Alignment of left and right sliding door			
C. Labor			
1. Pull down timing cover to remove and replace, drive belt, 3 pcs idler bearing and idler tensioner	1 lot	4,500.00	4,500.00
2. Alignment and camber correction for front and rear wheel	1 lot	2,800.00	2,800.00
Sub-Total			35,300.00
IV. Toyota Vios SAA 7829:			
A. Parts/Consumable to be supplied:			
Brake pad - front	1 set	1,800.00	1,800.00
B. Labor:			
Replacement of brake pad	1 lot	700.00	700.00
Sub-Total			2,500.00
		GRAND TOTAL (VAT inclusive)	₱98,940.00

Approved Budget : ₱ 98,940.00 (VAT Inclusive)

Mode of Procurement : Small Value Procurement

Submission of Quotation and Eligibility Requirements : February 26, 2024

Eligibility Requirements :

1. Valid and current Mayor's Permit (certified true copy)
2. PhilGEPS Registration Certificate (certified true copy) or PhilGEPS Registration Number
3. Omnibus Sworn Statement (Notarized and accordance with GPPB Circular 04-2020 dated September 16, 2020)

Note: In lieu of the Mayor's Permit and PhilGEPS Registration Number, you may submit a valid Certificate of PhilGEPS Registration (Platinum Membership).

Please submit your quotation and eligibility requirements in a sealed envelope at the address stated below.

Name of Bidder:

BIDS AND AWARDS COMMITTEE

National Development Company

7/F NDC Building, 116 Tordesillas St.

Salcedo Village, Makati City

Fax: 840-4862

Attention: BAC Secretariat

Reference Number: MR24-02-025

All prices should be VAT inclusive. Further, please indicate in the quotation the following:

1. Terms of Payment – Government Terms
2. Delivery Period – Five (5) calendar days
3. Warranty- three (3) months on defect and poor workmanship

(SIGNED)

AGM LEOPOLDO JOHN F. ACOT

Chairperson, Bids and Awards Committee